

GOVERNMENT OF ANDHRA PRAESH
A B S T R A C T

Public Service – Allegations of Irregularities in execution of works of repairs to Pedda cheruvu of Kesamudram(v) and 4 other Works under SGRY(SC)–Sri K.Rudra, Assistant Executive Engineer, Mahabubabad Mandal, Warangal Suspended from Service-reinstated – further action dropped - orders – Issued.

=====

IRRIGATION & CAD(SER.X-1)DEPARTMENT.

G.O.Rt.No. 289

Dated: 26-03-2011.

Read the following:

- 1) From the Dist.Collector, Warangal, Lr.Rc.No. A5/ 6778/ 2005, dt.25-11-06 addressed to the ENC, I & CAD and copy marked to Govt.
 - 2) G.O.Rt.No.1696, I & CAD(Ser.X-1) Dept.,dt.27-12-2006.
 - 3) Govt. Memo.No. 35734/Ser.X.1/2006-1, dt. 27.12.2006.
 - 4) G.O.Rt.No.298, I & CAD(Ser.X-1) Dept., Dated:17-03-2007.
 - 5) From the SE, IC Warangal, Lr.No. DEE/TSW/T4/273-75/1SC-1/ENC, dt. 24.05.2010
- :ooo:

O R D E R:

In the reference 1st read above, it was brought to the notice of the Government, that certain irregularities have been taken place in execution of the following works under SGRY(SC) by way of release of rice without executing the works:

- i) Repairs to Pedda cheruvu of Kesamudram(v)
- ii) Reparis to Ooracheruvu of Upperapally(V),
- iii) Repairs to Suraram Cheruvu of Venkatagiri(V) and
- iv) Repairs to Chittipaka Cheruvu of Ingurthy(V)

And whereas, orders were issued placing Sri K.Rudra, Assistant Executive Engineer, under suspension, pending initiation of disciplinary action against him on the reported irregularities committed in execution of works of Repairs to Peddacheruvu of Kesamudram(v) and 3 other Works under SGRY(SC). Simultaneously, in the reference 3rd read above, the CE, Minor Irrigation, Hyderabad has been requested to get the matter enquired and submit a detailed report, on the subject, for taking further action.

In the reference 4th read above, orders were issued revoking the suspension orders against Sri K.Rudra, Assistant Executive Engineer without prejudice to the disciplinary proceedings pending against him.

In the reference 5th read above, the Superintending Engineer ,Irrigation Circle, Warangal has submitted enquiry report stating that as per the instructions of the Chief Engineer, Minor Irrigation, Hyderabad, the Executive Engineer, Irrigation Division, Mahabubnagar has inspected and reported that, as per the site conditions and as reported by the Water Users Association Presidents and Ayakatdars the works have been carried out and the irrigation authorities have not followed any procedure and state away helped the contractors to lift the rice without execution of works is not substantiated, since, the works paid have been executed. Therefore, there is no financial loss to the Government in the execution of the said works. He has requested to drop further action in the matter.

Government after careful examination of the matter in detail it has been decided to drop further action against Sri K. Rudra, Assistant Executive Engineer by issue a warning. Accordingly, hereby order to drop further action against Sri K. Rudra, Assistant Executive Engineer and he is warned to be more careful in future.

The Engineer-in-Chief (Admn.Wing), Irrigation & CAD Department, Hyderabad shall take necessary action accordingly .

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

SHAILENDRA KUMAR JOSHI
PRINCIPAL SECRETARY TO GOVERNMENT

To
Sri K.Rudra, Assistant Executive Engineer,
through Engineer-in-Chief (Admn.Wing),
Irrigation & CAD Department, Hyderabad.
The Engineer-in-Chief (Admn.Wing)
Irrigation & CAD Dept., Hdyyerabad.
SF/SC.

//FORWARDED: : BY ORDER//

SECTION OFFICER